

SM2260 F/W Release Note

FW Package	MP Tool Version	ISP Version	Note
C2.0.8	V3.1.2	C2.0.8	<ul style="list-style-type: none">● Remove IEEE in Identify Controller and EUI64 in Identify Namespace.● Update NGUID for Win10 compatibility issue.● Shrink write cache size to 3MB.● Disable setup PERST GPIO20 interrupt.● Upgrade MP Tool to V3.1.2 and driver, "WinDrv2260_141700_20160921.zip".
C2.0.5	V3.1.0	C2.0.5	<ul style="list-style-type: none">● Enable "Whole Drive SLC Mode", which is configurable via MP Tool.● Bug fixes for PCIe 4-port Tester MFG SW.● Update MP Tool driver, "WinDrv2260_9941501_20160913.zip".
C2.0.0	V3.0.1	C2.2.0	<ul style="list-style-type: none">● Enable Intel L06B.● Update DRAM parameters.● Enable multi-port initialization on 4-port Tester.
C1.0.5	V2.2.2	C1.0.5	<ul style="list-style-type: none">● Initial FW release, including MPTool and EZTool.● Support Micron L06B.

Note:

1. F/W and ISP update is recommended.
2. History # is denoted by "Version-Date".

This document is for information only and is subject to change without notice. Silicon Motion, Inc. reserves the right to make changes in the product design without reservation and without notice to its users.