

SM2260 L06B F/W Release Note

FW Package	MP Tool Version	ISP Version	Note
C2.1.6	V3.2.0	C2.1.6	<ul style="list-style-type: none"> ● Rollback to use Set Feature to switch between SLC and TLC modes since some NAND parts may not be capable of 0xDA/0xDF commands. ● Add 2-steps PS4 feature. The number of PS3 stay time in LightSwitch is used to toggle this feature (e.g. number != 0 to enable; number = 0 to disable). ● Update MPTool to support 2x 4-port tester (cascaded as 8-port tester). ● Enable NAND ODT features. ● Disable L0s support in ASPM by default (configurable in MPTool). ● Bug fixes for 2TB drive and enhance error recovery statistics for 2TB configuration. ● Update SMI drive to "WinDrv2260_141800_20161024.zip". ● Update EZTool to "EzTools_2260_Micron_P1114A_V1.2.12".
C2.1.3	V3.1.3	C2.1.3	<ul style="list-style-type: none"> ● Snap Read enablement, code optimization, and Flash command process flow optimization for random performance enhancement (mainly for 1024GB). ● Enable 2TB support. ● Enable P-Fail feature (needs PCB power circuit to support). ● Enhance sequential write performance (especially 128/256GB) by changing ultra-block RAID to super-block, cache program, and DA/DF commands. Due to higher RAID overhead, the "binary capacity" would be not achievable. ● Add features of MPTool, including new logs by date and bar code scan. ● Add configurability of APST in MPTool, and default is APST disabled.
C2.0.8	V3.1.2	C2.0.8	<ul style="list-style-type: none"> ● Remove IEEE in Identify Controller and EUI64 in Identify Namespace. ● Update NGUID for Win10 compatibility issue. ● Shrink write cache size to 3MB. ● Disable setup PERST GPIO20 interrupt. ● Upgrade MP Tool to V3.1.2 and driver, "WinDrv2260_141700_20160921.zip".
C2.0.5	V3.1.0	C2.0.5	<ul style="list-style-type: none"> ● Enable "Whole Drive SLC Mode", which is configurable via MP Tool. ● Bug fixes for PCIe 4-port Tester MFG SW. ● Update MP Tool driver, "WinDrv2260_9941501_20160913.zip".
C2.0.0	V3.0.1	C2.2.0	<ul style="list-style-type: none"> ● Enable Intel L06B. ● Update DRAM parameters. ● Enable multi-port initialization on 4-port Tester.
C1.0.5	V2.2.2	C1.0.5	<ul style="list-style-type: none"> ● Initial FW release, including MPTool and EZTool. ● Support Micron L06B.

Note:

1. F/W and ISP update is recommended.
2. History # is denoted by "Version-Date".

This document is for information only and is subject to change without notice. Silicon Motion, Inc. reserves the right to make changes in the product design without reservation and without notice to its users.