



ADATA

Firmware Release Notes

Version 1.0

WARNING:

This firmware release is only valid for
ADATA SP580 Solid State Drives
Firmware Version 1.0.0.17

This update tool is only available for FW1.0.0.5 / 1.0.0.8 compatibility enhancements
October 05, 2017



Issues resolved:

Item	Description
1	Disable UART as default config to enhance performance.
2	Improving error handle mechanism of read back FTA log content with time stamp from MP area of config table.