



**Silicon Motion, Inc.**

## **SM2242AC Test Program/ ISP Release Note**

**SM2242 Test Program and ISP Release Note:**

Release Date	ISP Version	ISP Check Sum	Test AP Version	Description
2009/11/18	AC:2009-11-06	<b>006FF992</b>	2009-11-18	SM2242AC FW formal release
2010/02/11	AC:2010-02-08	<b>0073A97F</b>	2010-02-08	SM2242AC new update features: <ul style="list-style-type: none"><li>1. Fix Samsung K9K8G, K9KAG read data issue in internal interleave mode.</li><li>2. Enable link table only use strong page in MLC Flash.</li><li>3. Add ISP Block Error Handle (Load ISP code with ECC failure, assign another ISP block to current ISP Block).</li></ul>
2010/03/12	AC: 2010-02-22	<b>0073AF3B</b>	2010-02-22	SM2242 formal release FW: <ul style="list-style-type: none"><li>1. Fix get status command issue on Hynix 32nm.</li><li>2. Check minimum spare block after adjusting capacity when initial card.</li><li>3. Modify controller to flash driving strength to be 3 level bases on flash number.</li></ul>