

SM2258 B16A F/W Release Note

| FW Package | MP Tool Version | ISP Version | Note |
|------------|--------------------|----------------|--|
| Q0713C | Q0717A | Q0713C | <ul style="list-style-type: none">● Modify for F2H map align issue.● Fix DST Routine sub-function● Modify SPOR flow● Fix CMD queue hang issue● Fix Write same out of range return wrong status● Fix performance degrade on 120GB with RAID on issue |
| Q0524A | Q0525A | Q0524A | <ul style="list-style-type: none">● Initial release of B16A. |

Note:

1. F/W and ISP update is recommended.
2. History # is denoted by "Version-Date".

This document is for information only and is subject to change without notice. Silicon Motion, Inc. reserves the right to make changes in the product design without reservation and without notice to its users.