

## SM2262 Flash F/W & ISP Release Information – Q1208A

### Introduction

This purpose of this document is to provide release information on the SM2246EN F/W and ISP release information

### Fix Coverage

- ☒ stands for the “new fix” or “new support” in the category
- ☐ stands for the “no-update” in the category

| <input checked="" type="checkbox"/> <b>Tester FW</b>   | <input checked="" type="checkbox"/> <b>Controller ISP</b>  |
|--|--|
| <input type="checkbox"/> <b>Yield Issue</b><br><input checked="" type="checkbox"/> <b>Flash Issue</b> <ul style="list-style-type: none"> <li><input type="checkbox"/> SLC Flash <ul style="list-style-type: none"> <li><input type="checkbox"/> Samsung Flash</li> <li><input type="checkbox"/> Toshiba/Sandisk Flash</li> <li><input type="checkbox"/> Intel/Micron Flash</li> <li><input type="checkbox"/> Hynix Flash</li> <li><input type="checkbox"/> Others</li> </ul> </li> <li><input checked="" type="checkbox"/> 3D TLC Flash <ul style="list-style-type: none"> <li><input type="checkbox"/> Samsung Flash</li> <li><input checked="" type="checkbox"/> Toshiba/Sandisk Flash</li> <li><input type="checkbox"/> Intel/Micron Flash</li> <li><input type="checkbox"/> Hynix Flash</li> </ul> </li> </ul> <input type="checkbox"/> <b>Compatibility issue</b><br><input type="checkbox"/> <b>Tester Bug Fix</b><br><input checked="" type="checkbox"/> <b>AP Bug Fix &amp; New Function</b><br><input checked="" type="checkbox"/> <b>Feature Enhance</b> | <input checked="" type="checkbox"/> <b>Yield Issue</b><br><input checked="" type="checkbox"/> <b>Flash Issue</b> <ul style="list-style-type: none"> <li><input type="checkbox"/> SLC Flash <ul style="list-style-type: none"> <li><input type="checkbox"/> Samsung Flash</li> <li><input type="checkbox"/> Toshiba/Sandisk Flash</li> <li><input type="checkbox"/> Intel/Micron Flash</li> <li><input type="checkbox"/> Hynix Flash</li> <li><input type="checkbox"/> Others</li> </ul> </li> <li><input checked="" type="checkbox"/> 3D TLC Flash <ul style="list-style-type: none"> <li><input type="checkbox"/> Samsung Flash</li> <li><input checked="" type="checkbox"/> Toshiba/Sandisk Flash</li> <li><input type="checkbox"/> Intel/Micron Flash</li> <li><input type="checkbox"/> Hynix Flash</li> </ul> </li> </ul> <input type="checkbox"/> <b>Compatibility issue</b><br><input checked="" type="checkbox"/> <b>ISP Bug Fix</b><br><input type="checkbox"/> <b>Feature Enhance</b> |

**ISP Revision History**

| Version | MP Tool version | ISP version | Note                     |
|---------|-----------------|-------------|--------------------------|
| Q1208A  | V3.3.31         | Q1208A      | 1. First release version |

**Note:**

1. F/W and ISP update is recommended.
2. History # is denoted by "Version-Date" .

This document is for information only and is subject to change without notice. Silicon Motion, Inc. reserves the right to make changes in the product design without reservation and without notice to its users.